

## Annexure D

### BUILDING SAFETY CERTIFICATE

No. BSC/2025-2026/07

Dated: 28/07/2025

It is certified that the existing building Rajmata Sr. Sec. School, Shail Farm (name of the building or premises) at Shail Farm, Farsuki Nagal, Gurugram - Haryana (address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	<u>G+1</u>	<u>-</u>	<u>-</u>	<u>-</u>	<u>-</u>	<u>-</u>

The building is owned/occupied by Rajmata Sr. Sec. School, Shail Farm, Farsuki Nagal (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of P.W.D., B.I.R. Gurugram (Name of Department/ Govt.) on 25/07/2025 (date of inspection) in the presence of Mahipal, Principal, Rajmata Sr. Sec. School, Farsuki Nagal (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from 28/07/2025 for a period of one (01) years in accordance with rule and subject to compliance of the specific conditions as appended.

1. Fire Safety Report should be done respectively by the authorized by fire office Gurugram.
2. Structural stability has been examined with reference to the local altitude and intensity of wind load.
3. to the local altitude and intensity of wind load.
4. to the local altitude and intensity of wind load.

Issued on 28/07/2025 at Gurugram (Haryana)

\* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

  
**Executive Engineer**  
 Provincial Division No. I  
 PWD B&R Br., Gurugram

Signature with Seal : \_\_\_\_\_  
 Name : \_\_\_\_\_  
 Designation : \_\_\_\_\_  
 Name & Address of Department/ Office: \_\_\_\_\_